



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

SWA3-2
Job Sheet 183310



Part No: SWA3-2

Job Qty: 1 ea

Part Name: Electric Swivel 3,000 lb Safe Work Load (1,360 Kg)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 9/15/18

Job Tracking No:

Due Date: 11/9/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG SWA3 Rev 3

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		11/9/18	0.00	0.00	Start Up Small Fab-2		
110	Small Fab	1 pcs		11/9/18	0.00	2.00	Small Fab-6		
120	QC	1 pcs		11/9/18	0.00	0.00	QC5		
125	DC	1 pcs		11/9/18	0.00	0.00	DC		
130	Packaging	1 pcs		11/9/18	0.00	0.00	Packaging3		
140	QC21-FG	1 Ea		11/9/18	0.00	0.00	QC21		

Part Op 110 - Assemble as per DWG. Sheet 1 ***All assembly to be done in accordance with SWA3 swivel manual*** Engrave Descriptions: T/N And / or S/N number as required Using Marktronic engraver as per DWG. Laser engrave dart logo as per DWG.

125 - Photocopy blue file OM & OOPM-SWA3A Rev3

130 - Bag and tag

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
188-FPSS-832-3/8	Set Screw	1 Ea (1 ea)	90-Start up Operation	5027242
92210A303	Flat Socket Cap Screw	4 pcs (4 ea)	110-Small Fab	5083914
EL-PLUG-F	3-Prong Female Spade Plug	1 Ea (1 ea)	110-Small Fab	5072958
EL-PLUG-M	3-Prong Male Spade Plug	1 Ea (1 ea)	110-Small Fab	5072957
EL314-SJTOW	Long Line Electrical Wire, 14/3 Gauge	6 ft (6 ea)	110-Small Fab	5047767
SWA3-100	Upper End - Swa3 Swivel	1 Ea (1 ea)	110-Small Fab	5029397
SWA3-200	Lower End	1 Ea (1 ea)	110-Small Fab	5024348
SWA3-300	Wire Clamp	2 Ea (2 ea)	110-Small Fab	5075875
SWA3-400	Button Head Screw	2 Ea (2 ea)	110-Small Fab	5108094
SWA3-500	Connector Bushing-230	1 Ea (1 ea)	110-Small Fab	5047401
SWA3-600	O-Ring	1 Ea (1 ea)	110-Small Fab	5097844
SWA3-700	9529K15 Bearing Balls - 1/4"	32 Ea (32 ea)	110-Small Fab	14x 5084068/18x 5068311
SWA6A-1900	1/4" Female Spade Connector	4 Ea (4 ea)	110-Small Fab	5043603
SWA6A-900A	Rotary Connector - 2 wire	1 pcs (1 ea)	110-Small Fab	5108762

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	188-FPSS-832-3/8	1	60	0
110-Small Fab	92210A303	4	84	0
	EL-PLUG-F	1	27	0

EL-PLUG-M	1	96	0
EL314-SJTOW	6	262	0
SWA3-100	1	10	0
SWA3-200	1	4	0
SWA3-300	2	25	0
SWA3-400	2	48	0
SWA3-500	1	0	0
SWA3-600	1	12	0
SWA3-700	32	800	0
SWA6A-1900	4	576	0
SWA6A-900A	1	18	0

Part Specifications


Specifications could not be found.

Loctite 242 m138766
Grease Aeroshell m138724
Silicone GE m138942

Plex 9/17/18 7:51 AM Dart.lajeunesse.marie

JAKI
AEROSPACE

Container No: S114210



Part: SWA3-2
Job No: 183310
Serial No/Batch: S114210
Revision: 3
Inspector:
Exp Date:
Instructions:

Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 09/27/18

Work Order 183310

Customer _____

Number of Wires 2Date 01/10/18Serial Number 5114210

Number of Cycles	Load (Lbs.)	Action	Pass/Fail
1	3,000	Check for Conductivity against all wires.	- Pass
1	3,000	Check all wires for grounding against swivel body.	- Pass
1	1,500	Check for Conductivity against all wires.	- Pass
1	1,500	Check all wires for grounding against swivel body.	- Pass
1	750	Check for Conductivity against all wires.	- Pass
1	750	Check all wires for grounding against swivel body.	- Pass
1	0	Check for Conductivity against all wires.	- Pass
1	0	Check all wires for grounding against swivel body.	- Pass

Test Conducted By: Francis Lacroix
TechnicianSignature: Sylvain Pauchet
QC 5 Small FAB / QA

Submit